

OKI Printer Driver Compatibility

OKI Printer Driver compatibility with Windows 8/Windows 8.1 and Windows Server 2012 / Windows Server 2012 R2

Version: 5

Date: 17 Apr. 2014

Table of Contents



Table of Contents	2
Introduction	3
Explanation of Terms	4
Color Printer	5
Mono Printer	9
Multi Function Printer	10
Dot Matrix Printer	14
Software Applications	15
Operating Condition	17
Note when upgrading to Windows 8.1	18

Introduction



Following the launch of Windows 8/8.1 and Windows Server 2012/2012 R2, please find details of the compatibility of drivers and software applications related to OKI's portfolio of color, mono and dot matrix printers and multifunctional devices.

If your printer or MFP model is not listed, please contact your local OKI support representative.

means: Supported
 means: Requires Driver Updater

If there is no \bullet or \diamond in the box beside the product it means that the driver option is not supported.

Explanation of Terms



Built-in Driver

- Refers to the driver included in the Windows 8/8.1 operating system, these
- drivers are also referred to as "in-box drivers" or "in-OS drivers"
- Automatically installs for printers that are on a non-domain network with 30
- devices or less
- Most printers with a built-in driver use the OKI PCL6 Class Driver
- Supports x32, x64 and ARM
- This is the only driver option for Windows RT (ARM processor) tablets
- If Built-in Driver is Supported: The Windows 8 built-in driver at time of purchase
- can be used

Windows Update:

• Automatically installs the driver when the computer has an internet connection

OKI Driver*

- Full feature driver available on the OKI website
- Supports x32 and x64 (**may require Driver Updater)
- * There may be some feature limitations with the Windows 7/Vista driver under Windows 8 and Windows 8.1 operating system
- ** Driver Updater (x64 only): This is the update program that allows you to use the driver for Windows 7 x64 on Windows 8 x64 and Windows Server 2012.
- Please install the Windows 7 x64 driver first and then run the driver updater (available on the website by searching for Utilities and Windows 8 x64).
- Double-click on the downloaded file and if "User Account Control" is displayed; click [Yes]. Then follow the steps to install the software.

Windows Server 2012 / Windows Server 2012 R2

Windows Server 2012/Windows 2012 R2 only runs on 64-Bit processors, therefore please refer to the 64bit column only.



		1.00			OKI Driver	availability		
Model	Driver	Windows Built-in	Windows - Update	Win 7	/ Vista	1	Win 8.1	Note
	Туре	Driver	Driver	32bit	64bit	32bit	64bit	
	GDI					•	•	
C301	XPS							
	GDI					•	•	
C310	XPS							
C3100	GDI							
C3200	GDI							
	PCL	•				•	•	
C321	PS					•	•	
	XPS							
	PCL	•				•	•	
C330	PS					•	•	
	XPS							
C3300	GDI			•	♦			
	PCL	•				•	•	
C331	PS					•	•	
	XPS							
C3400	GDI			•	\$			
C3450	GDI			•	\$			
	PCL	•		•	•			4
C3600	PS			•	•			4
C3600	XPS							
0540	GDI					•	•	
C510	XPS							
0544	GDI					•	•	
C511	XPS							
C5100	GDI							
C5200	GDI							
C5250	GDI							
	PCL	•				•	•	
C530	PS					•	•	
	XPS							
CE200	PCL		•					1
C5300	PS		•					
	PCL	•				•	•	
C531	PS					•	•	
	XPS							
05.405	PCL	•	•					
C5400	PS		•					



		MCd	MCl		OKI Driver	availability		
Model	Driver	Windows Built-in	Windows Update Driver	Win 7	Win 7 / Vista Win 8 /			Note
	Туре	Driver		32bit	64bit	32bit	64bit	
05.450	PCL	•						
C5450	PS							
C5600	GDI			•	•			4
C5650	GDI			•	•			4
C5700	PCL	•		•	•			4
C5700	PS			•	•			4
C5750	PCL	•		•	•			4
C5750	PS			•	•			4
C5800	GDI			•	•			4
C5850	GDI			•	•			4
C5900	PCL	•		•	•			4
C3900	PS			•	•			4
C5950	PCL	•		•	•			4
C5950	PS			•	•			4
	PCL	•				•	•	
C610	PS					•	•	
	XPS							
	PCL	•		•	•			3,4
C710	PS			•	•			4
	XPS							
C7100	PCL		•					1
C7100	PS		•					
	PCL	•				•	•	
C711	PS					•	•	
	XPS							
C711WT	PS			•	•			4
C7200	PCL		•					
C7200	PS		•					
67200	PCL		•					1
C7300	PS		•					
C7350	PCL	•	•					
C/35U	PS		•					
C7400	PCL		•					
C/400	PS		•					
C7E00	PCL		•					1
C7500	PS		•					
C901	GDI			•	•			4
C801	XPS							
0010	GDI					•	•	
C810	XPS							



Driver Type PCL	Windows Built-in Driver	Windows - Update	Win 7	/ Viete	\\/: 0 /	1477 0 4	
PCL	Driver	Deixon	Win 7 / Vista Win 8			Win 8.1	Note
		Driver	32bit	64bit	32bit	64bit	
	•		•	•			3,4
PS			•	•			4
XPS							
PCL	•				•	•	
XPS							
PCL	•				•	•	
PS					•	•	
XPS							
PCL	•				•	•	
PS					•	•	
XPS							
PCL	•				•	•	
PS					•	•	
XPS							
GDI					•	•	
PCL	•				•	•	
PS		•			•	•	
PCL	•				•	•	
PS					•	•	
PS			•	•			4
PCL		•					
PS		•					
PCL			•	•	not released	not released	4
PS			•	•			
PCL		•					1
PS		•					
PCL		•					
PS		•					
PCL		•					1
PS		•					
PCL	•		•	•			4
PS			•	•			4
PCL	•		•	•			2,3,4
PS			•	•			2,4
PCL	•		•	•			2,4
PS			•	•			2,4
			•	•			4
	XPS PCL PS XPS PCL PS XPS PCL PS AXPS GDI PCL PS	XPS PCL • PS . XPS . PCL • PS . XPS . GDI . PCL • PS . PCL . PS	XPS • PCL • PS . XPS . PCL • PS . XPS . GDI . PCL • PS . PCL . PS . PCL .	XPS • • PS XPS PCL PS PS	PCL • PS . XPS . PCL • PS . XPS . PCL • PS . XPS . GDI . PCL • PS . PCL . PS . PCL .	XPS •	XPS .



	PCL		•	•			2,4
C9850	PS		•	•			۷,٦
	PCL	•	•	•			4
ES2032	PS	•					4
	PCL	_	•	•			4
ES2232	PS	•	•	•			4
	PCL	•	•	•			7
ES2426	PS	•					
	PCL	•			•	•	
ES2632a3	PS	•			•	•	
	PCL	•	•	•	•		3,4
ES3032	PS		•	•			4
	PCL	•	•	•			4
ES3640	PS		•	•			4
	PCL	•	•	•			2,4
ES3640a3	PS		•	•			2,4
F00/40	PCL		•	•			4
ES3640 Pro	PS		•	•			
	PCL	•			•	•	
ES5430	PS				•	•	
	XPS						
	PCL	•			•	•	
ES5431	PS				•	•	
	XPS						
	PCL	•			•	•	
ES6410	PS				•	•	
	XPS						
E60430	PCL	•	•	•			3,4
ES8430	PS		•	•			4
	PCL	•			•	•	
ES8431	PS				•	•	
	XPS						
	PCL	•			•	•	
ES8441	PS				•	•	
	XPS						

Mono Printer



PCL PCL PCL PCL XPS PCL PCL XPS PCL PCL XPS PCL PCL XPS	Windows Built-in Driver	Windows Update Driver	Win 7 32bit	/ Vista 64bit •	Win 8 / 32bit •	Win 8.1 64bit •	Note
PCL PCL XPS PCL PCL XPS PCL PCL XPS PCL XPS PCL XPS	•		•	•	•	•	
PCL PCL XPS PCL PCL XPS PCL PCL XPS PCL PCL	•	•					
PCL XPS PCL PCL XPS PCL XPS PCL	•	•			•	•	
XPS PCL PCL XPS PCL PCL PCL	•	•					
PCL PCL XPS PCL PCL		•	•	•			
PCL PCL XPS PCL PCL		•	•	•			
PCL XPS PCL PCL	•	•					
XPS PCL PCL	•					İ	1
PCL PCL					•	•	
PCL		ļ					
		•					1
PCL		•					1
	•				•	•	
PS					•	•	
PCL		•					1
PS		•					
PCL	•				•	•	
PS	♦				•	•	
XPS	♦						
PCL		•					1
PS		•					
PCL	•				•	•	
PS					•	•	
PCL			•	•			1,4
PCL					•	•	-
PS					•	•	
PCL	•				•	•	
PS					•	•	
PCL	•				•	•	
PS					•	•	
XPS							
PCL	•				•	•	
PS							
PCL	•						
	,						
_ P	PS PCL PCL PS PC	PS PCL PS	PS	PS	PS	PS	S



		Miller desert	Windows -		OKI Driver	availability		
Model	Driver	Windows Built-in	Update Driver	Win 7	/ Vista	Win 8 /	Win 8.1	Note
	Туре	Driver		32bit	64bit	32bit	64bit	
	Scanner							
C3520MFP	GDI					•	•	
	Scanner							
C3530MFP	GDI					•	•	
	FAX			OKI I	Driver			
	Scanner							
C5510MFP	GDI							
	Scanner							
C5540MFP	PCL	•		•	•			4
	PS			•	•			4
	Scanner							
C5550MFP	PCL	•		•	•			4
	PS			•	•			4
	PCL			•	•			4
C9800MFP	PS			OKI I	Driver			
	PCL			•	•			4
C9850MFP	PS			OKI I	Driver			
	FAX			OKI I	Driver			
	Scanner			OKI I	Driver			
MB460	PCL	•		•	•			4
	Scanner			OKI I	Driver			
MB461	PCL	•				•	•	
	XPS							
	Scanner			OKI [Driver			
	PCL	•		•	•			4
MB470	PS			•	•			4
	FAX			OKI I	Driver			
	Scanner			OKI I	Driver			
	PCL	•				•	•	
MB471	PS					•	•	
	XPS							
	FAX					OKI I	Driver	
	Scanner			•	•			
	PCL	•		•	•			4
MB480	PS			•	•			4
	FAX			•	•			

[•] Supported \diamond Requires Driver Updater



				OKI Driver availability					
Model	Driver	Windows Built-in	Windows Update Driver	Win 7	/ Vista		Win 8 / Win 8.1		
	Туре	Driver		32bit	64bit	32bit	64bit	=	
	Scanner			OKI I	Driver				
	PCL	•				•	•		
MB491	PS					•	•		
	XPS								
	FAX					OKI I	Driver		
	Scanner			OKI I	Driver	OKI I	Driver		
	PCL			OKI I	Driver	OKI I	Driver		
MB760 MB770	PS			OKI I	Driver	OKI I	Driver		
WIB770	XPS			OKI I	Driver	OKI I	Driver		
	FAX			OKI Driver		OKI I	Driver		
	Scanner								
MC350	GDI			•	•			4	
	Scanner			OKI I	Driver				
	PCL	•				•	•		
MC351	PS					•	•		
	XPS								
	Scanner					OKI I	l Driver		
	PCL	•				•	•		
MC352	PS					•	•		
	XPS								
	Scanner								
MC360	GDI			•	•			4	
	FAX			•	•				
	Scanner			OKI I	l Driver				
	PCL	•				•	•		
MC361	PS	-				•	•		
Wiodo I	XPS						-		
	FAX			OKI I	l Driver				
	Scanner			- CAT		OKT) Driver		
	PCL	•				• OKI I	•		
MC362	PS					•	•		
10002	XPS								
	FAX					OKI	Driver		
	Scanner) 		
	PCL	•		•	•			4	
MC560	PS	 		•	•			4	
	FAX				Driver			7	
	FAX			UKI I	וויע				

[•] Supported \diamond Requires Driver Updater



					OKI Driver	availability		
Model	Driver	Windows Built-in	Windows - Update	Win 7	Note			
	Туре	Driver	Driver	32bit	64bit	32bit	64bit	
	Scanner			OKI I	Driver			
	PCL	•				•	•	
MC561	PS					•	•	
	XPS							
	FAX			OKI I	Driver			
	Scanner					OKI	Driver	
	PCL	•				•	•	
MC562	PS					•	•	
	XPS							
	FAX					OKI	Driver	
	Scanner			OKI I	Driver	OKI	Driver	
	PCL			OKI I	Driver	OKI Driver		
MC760 MC770	PS			OKI I	Driver	OKI Driver		
MC780	XPS			OKI Driver OKI Driver		Driver		
	FAX			OKI I	Driver	OKI	Driver	
	Scanner			OKI I	Driver			
	PCL	•		•	•			4
MC851	PS			•	•			4
	FAX				l Driver			
	Scanner				Driver			
	PCL	•				•	•	
MC860	PS					•	•	
Wicooo	XPS							
	FAX			OKI	Driver			
	Scanner	_			Oriver 			4
	PCL	•		•	•			4
MC861	PS			•	•			4
	XPS							
	FAX			OKI I	Oriver I			
	Scanner							
ES1624MFP	PCL	•		•	•			4
	PS			•	•			4
	Scanner							
ES2032MFP	PCL	•		•	•			4
	PS			•	•			4
	Scanner			OKI I	Oriver T			
ES3451MFP	PCL	•				•	•	
ESSAS HVII P	PS					•	•	
	XPS							



		Maria da como	Miles desert		OKI Driver	availability		
Model	Driver Type	Windows Built-in	Windows - Update	Win 7	/ Vista	Win 8 /	Win 8.1	Note
	Турс	Driver	Driver	32bit	64bit	32bit	64bit	
	Scanner					OKI	Driver	
	PCL	•				•	•	
ES3452 MFP	PS					•	•	
	XPS							
500/401455	PCL			•	•			4
ES3640 MFP	PS			OKI I	Driver			
	Scanner			OKI I	Driver	OKI	Driver	
	PCL			OKI I	Driver	OKI	Driver	
ES7170	PS			OKI I	Driver	OKI	Driver	
	XPS			OKI I	Driver	OKI	Driver	
	FAX			OKI Driver		OKI Driver		
	Scanner			OKI I	Driver	OKI	Driver	
	PCL			OKI I	Driver	OKI	Driver	
ES7470 ES7480	PS			OKI I	OKI Driver		Driver	
	XPS			OKI Driver		OKI	Driver	
	FAX			OKI I	Driver	OKI	Driver	
	PCL			OKI I	Driver	OKI	Driver	
ES9160	PS			OKI [Driver	OKI Driver		
ES9170	XPS			OKI [Driver	OKI Driver		
	FAX			OKI I	Driver	OKI	Driver	
	PCL			OKI [Driver	OKI	Driver	
ES9460	PS			OKI [Driver	OKI	Driver	
ES9470	XPS			OKI [Driver	OKI	Driver	
	FAX			OKI I	Driver	OKI	Driver	
	Scanner			OKI I	Oriver	Windows 8: l Windows 8.1:	Jse OKI Driver Not supported	
ES9455	PCL			OKI I	Driver	OKI	Driver	
ES9465 ES9475	PS			OKI I	Driver	OKI	Driver	
	XPS			OKI I	Driver	OKI	Driver	
	FAX			OKI I	Driver	OKI	Driver	

13

Dot Matrix Printer



Model	Built-in Driver	Windows Update	OKI Support	Note
ML280elite	•	•		
ML320elite		•		
ML321elite		•		
ML380elite		•		
ML390elite		•		
ML391elite		•		
ML393elite		•		
ML395elite		•		
ML520elite		•		
ML521elite		•		
ML3320	•	•	Use the latest driver in CD or web site	
ML3321	•	•	Use the latest driver in CD or web site	
ML3390	•	•	Use the latest driver in CD or web site	
ML3391	•	•	Use the latest driver in CD or web site	
ML3410elite		•		
ML5100FB	•		Use the latest driver in CD or web site	
ML5520	•	•	Use the latest driver in CD or web site	
ML5521	•	•	Use the latest driver in CD or web site	
ML5590	•	•	Use the latest driver in CD or web site	
ML5591	•	•	Use the latest driver in CD or web site	
ML6300FB	•	•	Use the latest driver in CD or web site	
ML6300FB-SC	•		Use the latest driver in CD or web site	

Operating Condition



Note 1:

You may be able to select this model using the Windows 8 and Windows 8.1 built-in driver, however although the driver will appear to have installed, nothing will print. For this reason, the model is displayed as 'Not Supported'.

Note 2:

The Driver Installer is contained in the web package; therefore it cannot be completed by USB installation. To close the Driver Installer window awaiting PnP, you need to click the Cancel button thereafter the PnP.

Note 3:

Printing is disabled from the MPT (Multi-Purpose Tray) in Windows Store apps. To print from MPT, select MPT for Source on the printer's operator panel and then select [Automatically Select] for Source before printing.

Note 4:

Windows 8/ 8.1 64bit/Windows Server 2012/Windows Server 2012 R2: Use the driver for Windows7. Install OKI Driver Updater [0001] after you install the driver for Windows 7.

Software Applications



Please find below the scheduled availability of updated software applications.

- No shortcut will be added to the Metro UI at installation unless a file extension is EXE.
- An uninstaller shortcut is not added to the Metro UI.
- No plan to support utilities in Windows RT.

	Application	Availability of updated software	Note				
	Print Job Accounting	Support under consideration	Α				
	Print Job Accounting Enterprise	Support under consideration	Α				
ē	PrintSuperVision (.NET)	Support under consideration					
Server	PrintSuperVision (ME) *Japan only	The current version posted on the Web can be used with restrictions.	А, Е				
	Web Driver Installer	The current version posted on the Web can be used with restrictions.	A, E				
	Configuration Tool	The current version posted on the Web can be used with restrictions.	А				
	Colour Access Policy Manager	No plan to support					
	MFP Setup Tool	No plan to support					
_	Network Card Setup	Released					
Setting	Network Setup Tool	No plan to support					
Se	Panel Language Setup	The current version posted on the Web can be used with restrictions.	В				
	Printer Menu Setup Tool	The current version posted on the Web can be used with restrictions.	Α				
	Storage Device Manager	The current version posted on the Web can be used with restrictions.	А				
	Color Correct Utility	No plan to support					
oring		C3400n : The current version posted on the Web can be used with restrictions.	A, D				
Monitoring	Status Monitor	B2200 : The current version posted on the Web can be used with restrictions.					
		Other : Support under consideration. There exist some restrictions if the current version posted on the Web is used.	A, C, D				

• Supported ♦ Requires Driver Updater

Software Applications



	Application	Availability of updated software	Note
Print Support	Colour Correct Utility	The current version posted on the Web can be used with restrictions.	А
	Colour Swatch Utility	The current version posted on the Web can be used with restrictions.	А
	LPR Utility (OKILPR)	The current version posted on the Web can be used with restrictions.	А
	Network Extension	Released	А
	PDF Direct Print	Released	А
	Print Job Accounting Client	Released	
	Profile Assistant	The current version posted on the Web can be used with restrictions.	А
	PS Gamma Adjuster	Released	А
	Template Manager	Released	
	ActKey	Released	
Solution	AddressBook Viewer	Use the latest version posted on the Web.	А
	File Downloader	Use the latest version posted on the Web.	А
	e-Filing Backup-Restore	Use the latest version posted on the Web.	А
	Remote Scan driver	Use the latest version posted on the Web.	А
3rd-Party Solution	Hot Folder (v3)	Support under consideration	
	Command Workstation 4	Support under consideration	
	Command Workstation 5	Support under consideration	
	Network Card Setup (AdminManager)	Support under consideration	
	OKI Dot Impact Printer Utilities [OKI DIPUS]	Use the latest version posted on the Web.	
	OKI C3520MFP/C3530MFP/MC350/MC360	No plan to support	Α
	HotKey(C3520/30MFP , MC350/360)	No plan to support	
	PaperPort	Support under consideration	
	OmniPage	Support under consideration	
	C110 Remote Panel Utility	Support under consideration	
	C130 Status Panel Utility	Support under consideration	
	MC160 Setup Utility	Support under consideration	
	MC160 Scanner Utility	Support under consideration	



Operating Condition

Note A:

If the "Program Compatibility Assistant" dialog appears upon installation completion (including cancellation of installation), ensure to click [This program has successfully been installed]. When an installer or utility is launched, the [User Account Control] dialog will sometimes appear. Click [Yes] as it is necessary to run an installer or utility with permissions for administrators. With [No] clicked, neither the installer nor utility will launch.

Note B:

A supported version of the printer driver will become necessary.

Note C:

Print does not prompt it to automatically launch.

Note D:

Shortcut will NOT be added automatically at Start Screen when installing. It needs to be added manually.

Note E:

Windows Server 2012 R2: The expansion protected mode of Internet Explorer 11 is ON, so Web page cannot open.

Note when upgrading to Windows 8.1



1. Windows 7 to Windows 8.1

Printer Driver cannot be kept. (Automatically deleted) (See figure 2)

* Not only Oki but also the competitors will have same situation.

2. Windows 8 to Windows 8.1

If you choose "Keep Windows settings, personal files, and apps", Printer Driver will exist. (See figure 1)




Figure 1: Win 7 » Win 8 / Win 8 » Win 8.1




Figure 2: Win 7 » Win 8.1

Item	Win 7 » Win 8 / Win 7.1 » Win 8.1	Win 7 » Win 8.1
Keep Windows settings, personal files, and apps	Printer driver exist	N/A
Keep Personal file only	Printer driver deleted	Printer driver deleted
Nothing	Printer driver deleted	Printer driver deleted